

SECRET  
(When Filled In)

|  |       |   |   |       |                |
|--|-------|---|---|-------|----------------|
| Approved For Release 2002/07/10 : CIA-RDP78B04747A000900050095-4<br>CONTRACT INSPECTION REPORT   |       | CONTRACT NO.<br>78B04747A000900050095-4   | TASK NO.<br>25X1A                               |       |                |
| TO:<br>ENGINEERING SECTION/CB/PD/OL  |       | DATE<br>5 July 1963   | INSPECTION REPORT NO. (If final, so state)<br>9 |       |                |
|  |       | ESTIMATED COMPLETION DATE<br>January 1963   |   |       |                |
| NAME OF CONTRACTOR<br><div></div>  |       | 25X1A   |   |       |                |
| TYPE OF COMMODITY OR SERVICE<br><b>Stereo Comparator</b>   |       |   |   |       |                |
| THE CONTRACTOR IS ON SCHEDULE<br><input type="checkbox"/> YES <input checked="" type="checkbox"/> NO   |       | THE CONTRACTOR WILL PROBABLY REMAIN WITHIN ALLOCATED FUNDS<br><input checked="" type="checkbox"/> YES <input type="checkbox"/> NO       |   |       |                |
| THE CONTRACTOR WILL COMPLETE TASK WITHIN ALLOTTED TIME<br><input type="checkbox"/> YES <input checked="" type="checkbox"/> NO  |       | ALL PHASES OF THE TECHNICAL PROGRESS ARE SATISFACTORY<br><input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (See back) |   |       |                |
| HAS AN INTERIM REPORT, FINAL REPORT, PROTOTYPE, OR OTHER, END ITEM BEEN RECEIVED FROM THE CONTRACTOR DURING THE PERIOD? <input type="checkbox"/> YES <input type="checkbox"/> NO (If yes, give details on reverse side.)   |       |   |   |       |                |
| HAS GOVERNMENT-OWNED PROPERTY BEEN DELIVERED TO CONTRACTOR DURING THIS PERIOD? <input type="checkbox"/> YES <input type="checkbox"/> NO (If yes, indicate items, quantity, and cost on reverse side.)  |       |   |   |       |                |
| OVERALL PERFORMANCE OF CONTRACTOR  |       |   |   |       |                |
| 1. <input type="checkbox"/> OUTSTANDING 3. <input type="checkbox"/> EXCELLENT 5. <input checked="" type="checkbox"/> ACCEPTABLE 7. <input type="checkbox"/> UNSATISFACTORY<br>2. <input type="checkbox"/> SUPERIOR 4. <input type="checkbox"/> HIGHLY SATISFACTORY 6. <input type="checkbox"/> BARELY ADEQUATE |       |   |   |       |                |
| IF OVERALL PERFORMANCE OF CONTRACTOR IS UNSATISFACTORY OR BARELY ADEQUATE, INDICATE REASONS ON REVERSE SIDE.   |       |   |   |       |                |
| RECOMMENDED ACTION   |       |   |   |       |                |
| <input checked="" type="checkbox"/> CONTINUE AS PROGRAMMED <input type="checkbox"/> WITHHOLD PAYMENT PENDING SATISFACTORY PERFORMANCE<br><b>Declass Review by NIMA/DOD</b><br><input type="checkbox"/> TERMINATE <input type="checkbox"/> OTHER (Specify)  |       |   |   |       |                |
| IF TERMINATION IS RECOMMENDED OR IF THIS IS A FINAL REPORT, CERTIFY THAT ALL DELIVERABLE ITEMS UNDER THE CONTRACT HAVE BEEN RECEIVED. THESE INCLUDE, WHERE APPLICABLE, THE FOLLOWING:  |       |   |   |       |                |
| ITEM   | REC'D | DOES NOT APPLY  | ITEM  | REC'D | DOES NOT APPLY |
| PROTOTYPES   |       |   | MANUALS   |       |                |
| DRAWINGS AND SPECIFICATIONS  |       |   | FINAL REPORT                                    |       |                |
| PRODUCTION AND/OR OTHER END ITEMS  |       |   | SPECIAL TOOLING                                 |       |                |
|  |       |   | OTHER GOVERNMENT PROPERTY                       |       |                |
| DATE OF LAST CONTACT WITH CONTRACTOR<br>3 July 1963  |       |   |   | 25X1A |                |

25X1A This contract calls for the basic comparator to be built by [ ] 25X1A  
25X1A [ ] and the electric readout subcontracted to [ ] 25X1A  
25X1A [ ] Recent inquiries from [ ] 25X1A  
[ ] indicate they have begun working on the readout design but do  
not fully understand the requirements. Extensive data has been furnished  
them but this is a field they have not worked in before. Therefore,  
25X1A [ ] performance is considered barely acceptable. Performance by the  
25X1A [ ] is Highly Satisfactory. However, I feel they require  
improvement in their coordination of this project. Personal contact with  
25X1A [ ] designers may be necessary to further clarify and check the  
design.